



Order key for rotary synchronous motors

Stator (iron core with windings and cable):



Rotor:



Order example: Stator RP36-642-150-C-AS-3000-N0-A, Rotor RS36-642-150-A